

NAPAJENI
HLADINOMERU
KOMUNIKACE
RS 485


Hlavní vypínač

ZAPOJENI KONEKTORU X1

	CHOD		PORUCHA		AUTOMAT	
	SPIN.	ROZP.	SPIN.	ROZP.	SPIN.	ROZP.
CESLE 1	2	3	5	6	8	9
CESLE 2	11	12	14	15	17	18
CESLE 3	20	21	23	24	26	27
DOPRAVNIK 1	29	30	32	33	35	36
DOPRAVNIK 2	38	39	41	42	44	45
SIT	-	-	47	48	-	-
LIS	72	73	75	76	78	79
SPOLECNE	1,4,7,10,13,16,19,22,25,28 31,34,37,40,43,46,71,74,77					

PRIKLAD ZAPOJENI KONEKTORU X1:

CESLE 1



TITLE: S-16APard - USPORADANI STYKOVE JEDNOTKY

Document Number:

S - 0401

REV:

Date: 4.10.2012 14:22:34

Sheet: 1/1